



Calibration Procedure

PXIe-4150 and PXIe-4151

May 2025

379060A-01

Instructions on how to complete the
performance verification and
adjustment of your instrument.

This document contains the verification and adjustment procedures for the NI PXIe-4150 and PXIe-4151. Use the procedures in this document to automate calibration or to conduct manual calibration. Review and become familiar with the entire procedure before beginning the calibration process.





Contents

| | |
|---|----|
| 1. Icons..... | 2 |
| 2. Terms and Definitions..... | 3 |
| 3. Safety Guidelines..... | 3 |
| 4. Calibration Overview..... | 4 |
| 4.1. Safety Rated Current..... | 4 |
| 4.2. Safety Rated Voltages | 4 |
| 4.3. Calibration Information | 5 |
| 4.4. Calibration Condition Guidelines | 6 |
| 5. Calibration Resources..... | 7 |
| 5.1. Required Software | 7 |
| 5.2. Recommended Documentation | 8 |
| 5.3. Test Equipment | 8 |
| 6. Warm Up the DUT | 9 |
| 6.1. Perform Self-Calibration..... | 10 |
| 7. Perform Verification | 11 |
| 7.1. Voltage Programming and Measurement Accuracy Verification..... | 11 |
| 7.1.1. Test Limits | 11 |
| 7.1.2. Initial Test Connection | 12 |
| 7.1.3. Verification Procedure | 14 |
| 7.2. Current Programming and Measurement Accuracy Verification..... | 16 |
| 7.2.1. Test Limits | 16 |
| 7.2.2. Initial Test Connection | 17 |
| 7.2.3. Verification Procedure Direct to DMM | 19 |
| 7.2.4. Test Connection with Shunt | 21 |
| 7.2.5. Verification Procedure with Shunt | 22 |
| 7.3. Voltage Load Regulation Verification..... | 25 |
| 7.3.1. Test Limits | 25 |
| 7.3.2. Initial Test Connection | 26 |
| 7.3.3. Verification Procedure | 27 |

| | | |
|--------|---|----|
| 7.4. | Current Load Regulation Verification..... | 28 |
| 7.4.1. | Test Limits | 28 |
| 7.4.2. | Initial Test Connection..... | 29 |
| 7.4.3. | Verification Procedure | 30 |
| 8. | Perform Adjustment..... | 32 |
| 8.1. | Initialize for Adjust | 33 |
| 8.2. | Voltage Accuracy Adjustment Procedure | 33 |
| 8.2.1. | Initial Test Connection..... | 33 |
| 8.2.2. | Adjustment Procedure..... | 35 |
| 8.3. | Adjusting Current Accuracy Procedure | 37 |
| 8.3.1. | Initial Test Connection..... | 37 |
| 8.3.2. | Adjustment Procedure..... | 39 |
| 8.4. | Closing Adjustment Session | 41 |
| 8.5. | Running Self Cal | 41 |
| 9. | Perform Reverification..... | 42 |
| 10. | Update the Onboard Calibration Information..... | 42 |
| 11. | Revision History..... | 43 |
| 12. | NI Services | 43 |

1. Icons

Refer to the following descriptions if one of these icons is marked on your product or used in this guide.

| Icon | Description |
|---|--|
|  | Notice — Take precautions to avoid data loss, loss of signal integrity, degradation of performance, or damage to the product. |
|  | Caution — Take precautions to avoid injury. Consult the product documentation for cautionary statements when you see this icon printed on the product. Cautionary statements are localized into French for compliance with Canadian requirements. |
|  | Note — Important information to assist with execution of procedure. |
|  | NI Calibration Executive Users — Additional important information on running the automated procedure can be found in the help file. |

2. Terms and Definitions

| | |
|---|--|
| DUT | DUT is an acronym for Device Under Test and refers to the NI product being calibrated. For this procedure, DUT refers to the NI PXIe-4151 and PXIe-4150. |
| As-Found Limits | These limits are derived from the published specifications for the DUT. NI uses these limits to determine if the DUT is performing within the recommended calibration interval specifications at the time of calibration and before any adjustment is performed. |
| As-Left Limits | These limits are derived from the published specifications for the DUT minus guardband to ensure a high probability that the DUT will meet its specifications over the next recommended calibration interval. |
| Functional Test | Functional Tests determine whether the DUT is operating correctly. Functional tests are not directly related to performance specifications. |
| Verification | Verification evaluates the measured calibration results against the defined As-Found Limits. The result of the evaluation is expressed as a Pass/Fail condition in the calibration certificate using an established evaluation formula. |
| Adjustment | Adjustment performs a set of operations on the DUT to optimize the measurement performance and conform it to the assigned calibrated values. |
| Reverification | Reverification evaluates the measured calibration results against the As-Left limits after adjustment. The As-Left limits may be tighter than the As-Found limits. |
| Recommended Calibration Interval | This interval indicates the recommended period between each round of verification and adjustment of the DUT. There is a high probability that, within this interval, the DUT will remain within the published warranted performance specifications. Some measurement DUTs have warranted specifications for different calibration intervals, for example: 24 hours, 90 days, 1 year, and 2 years. In this case, the specification depends on the calibration cycle chosen by the user. |

3. Safety Guidelines



CAUTION

Observe all instructions and cautions in the user documentation. Using the product in a manner not specified can damage the product and compromise the built-in safety protection.

ATTENTION

Suivez toutes les instructions et respectez toutes les mises en garde de la documentation d'utilisation. L'utilisation du produit de toute autre façon que celle spécifiée risque de l'endommager et de compromettre la protection de sécurité intégrée.



CAUTION

The product is designed for nonhazardous, live signals. You must ensure that all signals connected to the product are isolated from hazardous, live circuits and no unsafe voltages are present at the inputs. Voltages that exceed the specifications could result in damage to the product or electric shock.

ATTENTION

Le produit est conçu pour les signaux en direct non dangereux. Vous devez vous assurer que tous les signaux connectés au produit sont isolés des circuits dangereux sous tension et qu'aucune tension dangereuse n'est présente aux entrées. Des tensions supérieures à celles mentionnées dans les spécifications peuvent endommager le produit ou provoquer un choc électrique

4. Calibration Overview

4.1. Safety Rated Current

| | |
|--------------------------------|---------------------------------|
| 101295A-01 | 1 A |
| 101296A-01 | 0 A |
| 101297A-01 | 20 A |
| 101271A-01 (HI SENSE LO SENSE) | 1 A |
| 101271A-01 (HI LO) | 40 A Total (20 A per Conductor) |

4.2. Safety Rated Voltages

| | |
|-------------------------------------|--------|
| All Cable Assemblies and Connectors | 60V DC |
|-------------------------------------|--------|

4.3. Calibration Information

Recommended Calibration Interval

2 years

Password

NI



Note

This is the default password for all password-protected operations. This password is site-specific.

| Task | Estimated Test Time | Operator Connections | Test Points | |
|------------------------------|---------------------|----------------------|----------------|----------------|
| | | | PXIe-4150 | PXIe-4151 |
| Setup | 3 minutes | 2 Connections | — | — |
| Warm Up | 30 minutes | — | — | — |
| Verify, Adjust, and Reverify | 72 minutes | 33 Connections | 84 test points | 80 test points |
| Verify Only | 23 minutes | 13 Connections | 38 test points | 36 test points |
| Adjust Only | 26 minutes | 7 Connections | 8 test points | 8 test points |



Note

This DUT requires special considerations when calculating the total warm up time for the system. Refer to the Warmup section in this document for more information.



Note

Estimated test times assume the user is conducting a manual calibration. For most procedures, automating the calibration significantly reduces test times.

**Note**

Always refer to the specifications document for your device before connecting signals. Failure to observe the specified maximum signal ratings can cause shock, a fire hazard, or damage to the device connected to the DUT.

**Note**

Before using any probes or accessories, ensure that they meet applicable safety requirements for the signal levels you may encounter.

| Environmental Conditions | Verification | Adjustment |
|---|--|--|
| Ambient temperature | $23\text{ }^{\circ}\text{C} \pm 5\text{ }^{\circ}\text{C}$ | $23\text{ }^{\circ}\text{C} \pm 1\text{ }^{\circ}\text{C}$ |
| Internal DUT temperature range ¹ | $T_{\text{cal}} \pm 5\text{ }^{\circ}\text{C}$ | $T_{\text{cal}} \pm 1\text{ }^{\circ}\text{C}$ |
| Relative humidity | Between 10% and 90%, noncondensing | |

4.4. Calibration Condition Guidelines

- Keep cabling as short as possible. Long cables act as antennas, picking up extra noise that can affect measurements.
- Ensure that all connections to the DUT, including front panel connections, and screws are secure.
- Allow adequate warm up time for all components of the calibration system.
- For maximum accuracy, perform the autocalibration (ACAL) function of the digital multimeter (DMM) prior to calibration if it has not been performed within the last 24 hours or when the multimeter's temperature changes by $\pm 1\text{ }^{\circ}\text{C}$ from the last autocalibration. Always disconnect any input signals before performing autocalibration. Perform ACAL for all functions.

¹ The internal temperature of the DUT is greater than the ambient temperature.

- Configure the DMM to the following settings for all measurements:
 - Set the DMM NPLC to **100**.
 - Set digits of resolution to **8.5**.
 - Set the front panel Guard switch to **LO**.
- Ensure that properties or attributes for the device that are not specified in calibration procedures are set to their default values.
- Make all connections as shown in diagrams.
- Ensure that the PXI/PXI Express chassis fan speed is set to HIGH, that the fan filters are clean, and that the empty slots contain filler panels. For more information, refer to the Maintain Forced-Air Cooling Note to Users document available at ni.com/manuals.
- If a DUT fails reverification after adjustment, ensure that the Test Conditions have been met before returning the DUT to NI.
- Clean any oxidation from the spade connectors or banana plugs on the cables before connecting them into the binding posts. Oxidation tarnishes the copper plugs so that they appear dull rather than shiny and leads to greater thermal EMF.

5. Calibration Resources

5.1. Required Software



Note

Ensure that the most recent version of the required driver software is installed before conducting the calibration.

Install the following software on the calibration system:

- LabVIEW version 2022 SPI Base/Full/Pro or later
- NI-DCPower instrument driver version 24.5.2 or greater

5.2. Recommended Documentation

Go to ni.com/docs to locate the following documentation for more information when performing this calibration:

- PXIe-4150 and PXIe-4151 User Manual
- PXIe-4150 and PXIe-4151 Specifications
- NI DCPower instrument driver help

5.3. Test Equipment

This section details the equipment NI recommends for each test performed as part of this calibration procedure.



NI Calibration Executive Users

Refer to the Calibration Executive Help to find an updated list of test equipment for this calibration procedure.



Note

NI recommend installing the DUT in a chassis with slot cooling capacity ≥ 58 W for increased module capability. The usage of slot blockers in the chassis will also increase cooling capability for the DUT.

| Standard | Recommended Model | Where Used | Functional Requirement(s) |
|--------------------------------------|---|---|--|
| Current Shunt ² | Ohm-Labs CS-50 | 7.2 Current Programming and Measurement Accuracy Verification | Resistance Accuracy Requires additional Calibration Test Points |
| DMM | Keysight 3458A | All Procedures | Current and Voltage Functionality |
| PXIe-4150/4151 Calibration Cable Kit | NI 789107-01 Kit Includes: <ul style="list-style-type: none"> • Cal Cable – “Spade”, Qty 1 • Cal Cable – “Banana”, Qty 1 • Cal Connector – “Shorting”, Qty 1 • Spade Jumper, Qty 2 • Red Spade-Banana Jumper, Qty 2 • Black Spade-Banana Jumper, Qty 2 | All Procedures | N/A |
| Auxiliary Power Supply | NI APS-4158 or NI APS-4159 | All Procedures | N/A |

6. Warm Up the DUT

Warm up time starts after the installed DUT is powered on in the chassis and power is applied through the 48 V auxiliary power supply. Warm up time resets after the DUT is power cycled or the auxiliary power supply is interrupted. This DUT requires 30 minutes to warm up prior to conducting

² Test Points should be included on the accredited calibration report for CS-50: 0.35 A, 1 A, 3 A, 5 A, 10 A, 20 A, 30 A, 40 A, and 50 A.

any tests. All cabling must be removed from the force and sense pins prior to running self-calibration. Self-calibration must be run after the DUT has sufficiently warmed up.

**Note**

Observe adequate Warm up time for all components of the calibration system.

6.1. Perform Self-Calibration

Self-calibration adjusts the DUT for variations in the module environment. Self-calibration should be performed after the DUT has warmed up for the entire recommended time period. Self-calibration is NOT required to be repeated during the procedure unless more than 24 hours have passed, or the ambient temperature has changed by more than 5 °C, or the DUT has been power-cycled, or the auxiliary power supply has been interrupted when providing power to the DUT.

Complete the following steps to conduct self-calibration using Measurement & Automation Explorer (MAX).

**Note**

The only supported values for the `Self Calibration Persistence` property and the `NIDCPOWER_ATTR_SELF_CALIBRATION_PERSISTENCE` attribute are **Write to EEPROM** and `NIDCPOWER_ATTR_VAL_WRITE_TO_EEPROM`, respectively. This setting saves the calibration data to the onboard EEPROM, so the corrections survive power cycling and device resetting. Because EEPROM has a limited number of write cycles, NI recommends that you save your self-calibration data to EEPROM no more than once per day. Disconnect all external signals before beginning self-calibration.

1. Install the DUT and let it warm up for the recommended warm-up time.

**Note**

Warm up begins when the PXI chassis has been powered on, the operating system has completely loaded, and auxiliary power is supplied to the DUT.

2. Self-calibrate the DUT by clicking the **Self-Calibrate** button in MAX.
3. Launch Measurement Automation Explorer (MAX).
4. Select **My System»Devices and Interfaces»[DUT model name]**.
5. Start self-calibration using one of the following methods:
6. Click **Self-Calibrate** in the upper right corner of MAX.
7. Right-click the name of the DUT in the MAX configuration tree and select **Self-Calibrate** from the drop-down menu.

**Note**

Low energy transients can appear at the output terminals of your DUT during certain situations, such as power-up, power-down, device driver loading, and self-calibration.

7. Perform Verification

7.1. Voltage Programming and Measurement Accuracy Verification

7.1.1. Test Limits

Table 1: Test Points/Limits for Voltage Programming and Measurement Accuracy Verification Test

| DUT Range | Test Point | DUT Model | Sense Configuration | As-Found Test Limit | |
|-----------|------------|----------------|---------------------|---------------------|-------------|
| | | | | Lower Limit | Upper Limit |
| 6 V | 100 mV | PXIe-4150/4151 | Local & Remote | – 0.522 mV | 0.522 mV |

| | | | | | |
|------|--------|----------------|----------------|------------|----------|
| 6 V | 1.5 V | PXIe-4150/4151 | Local & Remote | – 0.83 mV | 0.83 mV |
| 6 V | 3 V | PXIe-4150/4151 | Local & Remote | – 1.16 mV | 1.16 mV |
| 6 V | 6 V | PXIe-4150/4151 | Local & Remote | – 1.82 mV | 1.82 mV |
| 60 V | 100 mV | PXIe-4150 | Local & Remote | – 5.02 mV | 5.02 mV |
| 60 V | 5 V | PXIe-4150 | Local & Remote | – 6.20 mV | 6.20 mV |
| 60 V | 10 V | PXIe-4150 | Local & Remote | – 7.40 mV | 7.40 mV |
| 60 V | 20 V | PXIe-4150 | Local & Remote | – 9.80 mV | 9.80 mV |
| 60 V | 40 V | PXIe-4150 | Local & Remote | – 14.60 mV | 14.60 mV |
| 60 V | 60 V | PXIe-4150 | Local & Remote | – 19.40 mV | 19.40 mV |
| 20 V | 100 mV | PXIe-4151 | Local & Remote | – 2.02 mV | 2.02 mV |
| 20 V | 5 V | PXIe-4151 | Local & Remote | – 3.20 mV | 3.20 mV |
| 20 V | 10 V | PXIe-4151 | Local & Remote | – 4.40 mV | 4.40 mV |
| 20 V | 20 V | PXIe-4151 | Local & Remote | – 6.80 mV | 6.80 mV |

7.1.2. Initial Test Connection



Caution


Always refer to the specifications document for your device before connecting signals. Failure to observe the specified maximum signal ratings can cause a fire hazard or damage to the device connected to the DUT.



Caution

Before using any probes or accessories, ensure that they meet applicable safety requirements for the signal levels you may encounter.

Figure 1. Connections for Voltage Programming and Measurement Accuracy Verification



1. DUT
2. Auxiliary Power Supply
3. Auxiliary Power Supply Cable
4. Cal Cable – "Banana" (NI 101295A-01)
5. DMM
6. HI Sense signal cable
7. HI signal cable from DUT (Positive polarity defined as voltage measured on NI > LO)
8. LO Sense signal cable
9. LO single wire from DUT (Positive polarity defined as voltage measured on NI > LO)
10. AUX I/O Connector for DUT



Note

Before operating the programmable power supply, short pin 4 to pin 5 on the AUX I/O connector. For more information, refer to *Installing the Input and AUX I/O Connector on the PXIe-4151*.

7.1.3. Verification Procedure

1. Reset the DUT.
2. Ensure that the warm-up time is observed for the DUT as well as all the instruments.
3. Perform self-calibration on the DUT, if required. Follow instructions identified in this procedure regarding self-calibration.
4. Ensure DUT is not generating any signals, and the output is turned off prior to making any connections.
5. Set the DUT function to **DC Voltage**.
6. Connect all test equipment as shown in **Figure 1**.



Note

Before using any probes or accessories, ensure that they meet applicable safety requirements for the signal levels you may encounter.

Repeat 2 times, once for each sense configuration.

7. Set the level range, limit range, and limit on the DUT.
 - a. Set current limit to **100 mA**.
 - b. Set current range to **100 mA**.
8. Set the DUT sense attribute according to **Table 1**.
9. First iteration of loop should be **local**.

10. Second iteration of loop should be **remote**.
11. Set the DUT to **2 PLC** for measurement.
12. Commit all settings to DUT.
13. Configure the DMM
 - a. Set the DMM NPLC to **100**.
 - b. Set digits of resolution to **8.5**.
 - c. Set function to **DC Voltage**.



Note

Recommended to start with smallest signal level and iterate through test points according to increasing signal level.

Repeat 10 times, once for each output Voltage (PXIe-4150).
Repeat 8 times, once for each output Voltage (PXIe-4151).

14. Set the DMM to the voltage range according to **Table 2**.
15. Set the level of the DUT to the test point according to **Table 2**.



Note

Recommended to start with smallest signal level and iterate through test points according to increasing signal level.

Table 2: Voltage Test Point Configuration

| DUT Range | Test Point | DMM Range | DUT Model |
|-----------|------------|-----------|----------------|
| 6 V | 100 mV | 100 mV | PXIe-4150/4151 |
| 6 V | 1.5 V | 10 V | PXIe-4150/4151 |
| 6 V | 3 V | 10 V | PXIe-4150/4151 |
| 6 V | 6 V | 10 V | PXIe-4150/4151 |
| 20 V | 100 mV | 100 mV | PXIe-4151 |
| 20 V | 5 V | 10 V | PXIe-4151 |

| | | | |
|------|--------|--------|-----------|
| 20 V | 10 V | 10 V | PXIe-4151 |
| 20 V | 20 V | 100 V | PXIe-4151 |
| 60 V | 100 mV | 100 mV | PXIe-4150 |
| 60 V | 5 V | 10 V | PXIe-4150 |
| 60 V | 10 V | 10 V | PXIe-4150 |
| 60 V | 20 V | 100 V | PXIe-4150 |
| 60 V | 40 V | 100 V | PXIe-4150 |
| 60 V | 60 V | 100 V | PXIe-4150 |

16. Wait 2 seconds to ensure the system has adequate time to settle.
17. An additional 4 minute wait is required when the DMM has changed either function or range.



Note

The additional 4 minute wait is to reduce thermal EMF and a requirement of using the DMM identified in this procedure.

18. Take a voltage measurement using the DMM.
19. Calculate the measurement accuracy.

$$Voltage_{accuracy} = DMM_{measurement} - Test\ Point$$

20. Verify the accuracy measurement against the test limits in **Table 1**.

7.2. Current Programming and Measurement Accuracy Verification


7.2.1. Test Limits

Table 3: Test Points/Limits for Current Programming and Measurement Accuracy Verification Test

| DUT Range | Test Point | DUT Model | As-Found Test Limit | |
|-----------|------------|----------------|---------------------|--------------|
| | | | Lower Limit | Upper Limit |
| 100 mA | 25 mA | PXIe-4150/4151 | – 37.5 μ A | 37.5 μ A |
| 100 mA | 50 mA | PXIe-4150/4151 | – 45.0 μ A | 45.0 μ A |
| 100 mA | 100 mA | PXIe-4150/4151 | – 60.0 μ A | 60.0 μ A |
| 1 A | 250 mA | PXIe-4150/4151 | – 375 μ A | 375 μ A |
| 1 A | 500 mA | PXIe-4150/4151 | – 450 μ A | 450 μ A |
| 1 A | 1 A | PXIe-4150/4151 | – 600 μ A | 600 μ A |
| 10 A | 2.5 A | PXIe-4150 | – 3.87 mA | 3.87 mA |
| 10 A | 5 A | PXIe-4150 | – 5.75 mA | 5.75 mA |
| 10 A | 10 A | PXIe-4150 | – 9.5 mA | 9.5 mA |
| 25 A | 2.5 A | PXIe-4151 | – 3.6 mA | 3.6 mA |
| 25 A | 5 A | PXIe-4151 | – 5.3 mA | 5.3 mA |
| 25 A | 10 A | PXIe-4151 | – 8.5 mA | 8.5 mA |
| 25 A | 25 A | PXIe-4151 | – 18.3 mA | 18.3 mA |

7.2.2. Initial Test Connection

Figure 2. Initial Direct Connection to DMM for Current Programming and Measurement Accuracy Verification



1. DUT
2. Auxiliary Power Supply
3. Auxiliary Power Supply Cable
4. Cal cable - "Banana" (NI 101295A-01)
5. DMM
6. HI Sense signal cable
7. HI signal cable from DUT (Positive polarity defined as voltage measured on NI > LO)
8. LO Sense signal cable
9. LO single wire from DUT (Positive polarity defined as voltage measured on NI > LO)
10. AUX I/O Connector for DUT

**Note**

Before operating the programmable power supply, short pin 4 to pin 5 on the AUX I/O connector. For more information, refer to *Installing the Input and AUX I/O Connector on the PXIe-4151*.

7.2.3. Verification Procedure Direct to DMM

1. Reset the DUT.
2. Ensure that the warm-up time is observed for the DUT as well as all the instruments.
3. Perform self-calibration on the DUT, if required. Follow instructions identified in this procedure regarding self-calibration.
4. Ensure DUT is not generating any signals, and the output is turned off prior to making any connections.
5. Set the DUT to **DC Current** function.
6. Connect all test equipment as shown in **Figure 2**.

**Caution**

Before using any probes or accessories, ensure that they meet applicable safety requirements for the signal levels you may encounter.

Repeat 3 times, once for each output Current value.

7. Set the level range, limit range, and limit on the DUT.
 - a. Set voltage limit to **6 V**.
 - b. Set voltage range to **6 V**.
8. Set the DUT sense attribute according to **Table 3**.
9. Set the sense configuration to **local**.
10. Set the DUT to **2 PLC** for measurement.

11. Commit all settings to DUT.
12. Configure the DMM
 - a. Set the DMM NPLC to **100**.
 - b. Set digits of resolution to **8.5**.
 - c. Set function to **DC Current**.

**Note**

Recommended to start with smallest signal level and iterate through test points according to increasing signal level.

13. Set the DMM to the current range according to **Table 4**.
14. Set the level of the DUT to the test point according to **Table 4**.

**Note**

Recommended to start with smallest signal level and iterate through test points according to increasing signal level.

Table 4: Current Test Point Configuration

| DUT Range | Test Point | DMM Range | DUT Model |
|-----------|------------|-----------|----------------|
| 100 mA | 25 mA | 100 mA | PXIe-4150/4151 |
| 100 mA | 50 mA | 100 mA | PXIe-4150/4151 |
| 100 mA | 100 mA | 100 mA | PXIe-4150/4151 |


15. Wait 2 seconds to ensure the system has adequate time to settle.
16. An additional 30 second wait is required when the DMM has changed either function or range.
17. Take a current measurement using the DMM.
18. Calculate the measurement accuracy.

$$Current_{accuracy} = DMM_{measurement} - Test\ Point$$

19. Verify the accuracy measurement against the test limits in **Table 3**.

7.2.4. Test Connection with Shunt

Figure 3. Connection with Shunt for Current Programming and Measurement Accuracy Verification



-
- | | |
|---|--|
| 1. DUT | 8. HI Sense signal cable connected to Shunt HI current terminal |
| 2. Auxiliary Power Supply | 9. LO single wire from DUT (Positive polarity defined as voltage measured on NI > LO) connected to Shunt LO current terminal |
| 3. Auxiliary Power Supply Cable | 10. LO Sense signal cable connected to Shunt LO current terminal |
| 4. Cal cable – "Spade" (NI 101271A-01) | 11. Shunt HI Sense signal cable: Spade-Banana red (Pomona 5295-36-2) |
| 5. 50 A Shunt (0.01 Ω) | 12. Shunt LO Sense signal cable: Spade-Banana black (Pomona 5295-36-0) |
| 6. DMM | 13. AUX I/O Connector for DUT |
| 7. HI signal cable from DUT (Positive polarity defined as voltage measured on NI > LO) connected to Shunt HI current terminal | |



Note

Before operating the programmable power supply, short pin 4 to pin 5 on the AUX I/O connector. For more information, refer to *Installing the Input and AUX I/O Connector on the PXIe-4151*.

7.2.5. Verification Procedure with Shunt

1. Reset the DUT.
2. Ensure that the warm-up time is observed for the DUT as well as all the instruments.
3. Perform self-calibration on the DUT, if required. Follow instructions identified in this procedure regarding self-calibration.
4. Ensure DUT is not generating any signals, and the output is turned off prior to making any connections.
5. Set the DUT to **DC Current** function.
6. Connect all test equipment as shown in **Figure 3**.

**Caution**

Before using any probes or accessories, ensure that they meet applicable safety requirements for the signal levels you may encounter.

Repeat 6 times, once for each output Current (PXIe-4150).
Repeat 7 times, once for each output Current (PXIe-4151).

7. Set the level range, limit range, and limit on the DUT.
 - a. Set voltage limit to **6 V**.
 - b. Set voltage range to **6 V**.
8. Set the DUT sense attribute according to **Table 3**.
9. Set the sense configuration to **local**.
10. Set the DUT to **2 PLC** for measurement.
11. Commit all settings to DUT.
12. Configure the DMM
 - a. Set the DMM NPLC to **100**.
 - b. Set digits of resolution to **8.5**.
 - c. Set function to **DC Current**.

**Note**

Recommended to start with smallest signal level and iterate through test points according to increasing signal level.

13. Set the DMM to the voltage range according to **Table 5**.
14. Set the level of the DUT to the test point according to **Table 5**.

**Note**

Recommended to start with smallest signal level and iterate through test points according to increasing signal level.

Table 5: Current Test Point Configuration

| DUT Range | Test Point | Expected DMM Reading | DMM Range | DUT Model |
|-----------|------------|----------------------|-----------|----------------|
| 1 A | 250 mA | 2.5 mV | 100 mV | PXIe-4150/4151 |
| 1 A | 500 mA | 5 mV | 100 mV | PXIe-4150/4151 |
| 1 A | 1 A | 10 mV | 100 mV | PXIe-4150/4151 |
| 10 A | 2.5 A | 25 mV | 100 mV | PXIe-4150 |
| 10 A | 5 A | 50 mV | 100 mV | PXIe-4150 |
| 10 A | 10 A | 100 mV | 100 mV | PXIe-4150 |
| 25 A | 2.5 A | 25 mV | 100 mV | PXIe-4151 |
| 25 A | 5 A | 50 mV | 100 mV | PXIe-4151 |
| 25 A | 10 A | 100 mV | 100 mV | PXIe-4151 |
| 25 A | 25 A | 250 mV | 1 V | PXIe-4151 |

15. Wait 2 seconds to ensure the system has adequate time to settle.
16. An additional 4 minute wait is required when the DMM has changed either function or range.


Note

The additional 4 minute wait is to reduce thermal EMF and a requirement of using the DMM identified in this procedure.

17. Take a voltage measurement using the DMM.
18. Calculate the measurement accuracy.

$$Current_{accuracy} = \frac{DMM_{measurement}}{Shunt_{resistance}} - Test\ Point$$

19. Verify the accuracy measurement against the test limits in **Table 3**.

7.3. Voltage Load Regulation Verification


7.3.1. Test Limits

Table 6: Test Points/Limits for Voltage Load Regulation Verification Test

| DUT Range | Source Range | Test Point | DUT Voltage Limit | DUT Model | DUT Sense Mode | As-Found Test Limit | |
|-----------|--------------|------------|-------------------|-----------|----------------|---------------------|-------------|
| | | | | | | Lower Limit | Upper Limit |
| 6 V | 10 A | 2.5 A | 3 V | PXIe-4150 | Local | – 88 mV | 88 mV |
| 6 V | 10 A | 5 A | 3 V | PXIe-4150 | Local | – 176 mV | 176 mV |
| 6 V | 10 A | 10 A | 3 V | PXIe-4150 | Local | – 350 mV | 350 mV |
| 6 V | 10 A | 2.5 A | 3 V | PXIe-4150 | Remote | – 0.50 mV | 0.50 mV |
| 6 V | 10 A | 5 A | 3 V | PXIe-4150 | Remote | – 0.50 mV | 0.50 mV |
| 6 V | 10 A | 10 A | 3 V | PXIe-4150 | Remote | – 0.50 mV | 0.50 mV |
| 60 V | 10 A | 2.5 A | 30 V | PXIe-4150 | Remote | – 6.00 mV | 6.00 mV |
| 60 V | 10 A | 5 A | 30 V | PXIe-4150 | Remote | – 6.00 mV | 6.00 mV |
| 60 V | 10 A | 10 A | 30 V | PXIe-4150 | Remote | – 6.00 mV | 6.00 mV |
| 6 V | 25 A | 6.25 A | 3 V | PXIe-4151 | Local | – 69 mV | 69 mV |
| 6 V | 25 A | 12.5 A | 3 V | PXIe-4151 | Local | – 138 mV | 138 mV |
| 6 V | 25 A | 25 A | 3 V | PXIe-4151 | Local | – 275 mV | 275 mV |
| 6 V | 25 A | 6.25 A | 3 V | PXIe-4151 | Remote | – 0.50 mV | 0.50 mV |
| 6 V | 25 A | 12.5 A | 3 V | PXIe-4151 | Remote | – 0.50 mV | 0.50 mV |
| 6 V | 25 A | 25 A | 3 V | PXIe-4151 | Remote | – 0.50 mV | 0.50 mV |
| 20 V | 25 A | 6.25 A | 10 V | PXIe-4151 | Remote | – 2.00 mV | 2.00 mV |
| 20 V | 25 A | 12.5 A | 10 V | PXIe-4151 | Remote | – 2.00 mV | 2.00 mV |
| 20 V | 25 A | 25 A | 10 V | PXIe-4151 | Remote | – 2.00 mV | 2.00 mV |

7.3.2. Initial Test Connection

Figure 4. Initial Connection for Voltage Load Regulation Verification Test



1. DUT
2. Auxiliary Power Supply
3. Auxiliary Power Supply Cable
4. Cal Connector – Shorting (NI 101296A-01)
5. AUX I/O Connector for DUT



Note

Before operating the programmable power supply, short pin 4 to pin 5 on the AUX I/O connector. For more information, refer to *Installing the Input and AUX I/O Connector on the PXIe-4151*.

7.3.3. Verification Procedure

1. Reset the DUT.
2. Ensure that the warm-up time is observed for the DUT.
3. Perform self-calibration on the DUT, if required. Follow instructions identified in this procedure regarding self-calibration.
4. Ensure DUT is not generating any signals, and the output is turned off prior to making any connections.
5. Set the DUT to **DC Current** function.
6. Connect all test equipment as shown in **Figure 4**.



Caution

Before using any probes or accessories, ensure that they meet applicable safety requirements for the signal levels you may encounter.

Repeat 9 times, once for each current test point in Table 5.

7. Set the level range, limit range, and limit on the DUT according to **Table 5**.
8. Set the DUT sense attribute according to **Table 5**.
9. Set the sense configuration to **remote**.
10. Set the level of the DUT to the test point according to **Table 7**.

Table 7: Voltage Load Regulation Test Point Configuration

| DUT Voltage Range | DUT Sense Mode | DUT Source Range | Test Point | DUT Model |
|-------------------|----------------|------------------|------------|-----------|
| 6 V | Local | 10 A | 2.5 A | PXIe-4150 |
| 6 V | Local | 10 A | 5 A | PXIe-4150 |
| 6 V | Local | 10 A | 10 A | PXIe-4150 |

| | | | | |
|------|--------|------|--------|-----------|
| 6 V | Remote | 10 A | 2.5 A | PXIe-4150 |
| 6 V | Remote | 10 A | 5 A | PXIe-4150 |
| 6 V | Remote | 10 A | 10 A | PXIe-4150 |
| 60 V | Remote | 10 A | 2.5 A | PXIe-4150 |
| 60 V | Remote | 10 A | 5 A | PXIe-4150 |
| 60 V | Remote | 10 A | 10 A | PXIe-4150 |
| 6 V | Local | 25 A | 6.25 A | PXIe-4151 |
| 6 V | Local | 25 A | 12.5 A | PXIe-4151 |
| 6 V | Local | 25 A | 25 A | PXIe-4151 |
| 6 V | Remote | 25 A | 6.25 A | PXIe-4151 |
| 6 V | Remote | 25 A | 12.5 A | PXIe-4151 |
| 6 V | Remote | 25 A | 25 A | PXIe-4151 |
| 20 V | Remote | 25 A | 6.25 A | PXIe-4151 |
| 20 V | Remote | 25 A | 12.5 A | PXIe-4151 |
| 20 V | Remote | 25 A | 25 A | PXIe-4151 |

11. Set the DUT to **2 PLC** for measurement.
12. Commit all settings to DUT.
13. Wait 2 seconds to ensure the system has adequate time to settle.
14. Take a voltage measurement from the DUT.
15. Verify the accuracy measurement against the test limits in **Table 6**.

7.4. Current Load Regulation Verification


7.4.1. Test Limits

Table 8: Test Points/Limits for Current Load Regulation Verification Test

| DUT Range | Source Range | Test Point | DUT Model | As-Found Test Limit | |
|-----------|--------------|------------|-----------|---------------------|-------------|
| | | | | Lower Limit | Upper Limit |
| 100 mA | 60 V | 15 V | PXIe-4150 | – 0.03 mA | 0.03 mA |
| 100 mA | 60 V | 30 V | PXIe-4150 | – 0.03 mA | 0.03 mA |
| 100 mA | 60 V | 60 V | PXIe-4150 | – 0.03 mA | 0.03 mA |
| 1 A | 60 V | 15 V | PXIe-4150 | – 0.30 mA | 0.30 mA |
| 1 A | 60 V | 30 V | PXIe-4150 | – 0.30 mA | 0.30 mA |
| 1 A | 60 V | 60 V | PXIe-4150 | – 0.30 mA | 0.30 mA |
| 10 A | 60 V | 15 V | PXIe-4150 | – 0.70 mA | 0.70 mA |
| 10 A | 60 V | 30 V | PXIe-4150 | – 0.70 mA | 0.70 mA |
| 10 A | 60 V | 60 V | PXIe-4150 | – 0.70 mA | 0.70 mA |
| 100 mA | 20 V | 5 V | PXIe-4151 | – 0.03 mA | 0.03 mA |
| 100 mA | 20 V | 10 V | PXIe-4151 | – 0.03 mA | 0.03 mA |
| 100 mA | 20 V | 20 V | PXIe-4151 | – 0.03 mA | 0.03 mA |
| 1 A | 20 V | 5 V | PXIe-4151 | – 0.30 mA | 0.30 mA |
| 1 A | 20 V | 10 V | PXIe-4151 | – 0.30 mA | 0.30 mA |
| 1 A | 20 V | 20 V | PXIe-4151 | – 0.30 mA | 0.30 mA |
| 25 A | 20 V | 5 V | PXIe-4151 | – 2.00 mA | 2.00 mA |
| 25 A | 20 V | 10 V | PXIe-4151 | – 2.00 mA | 2.00 mA |
| 25 A | 20 V | 20 V | PXIe-4151 | – 2.00 mA | 2.00 mA |

7.4.2. Initial Test Connection

Figure 5. Initial Connection for Current Load Regulation Verification Test



1. DUT
2. Auxiliary Power Supply
3. Auxiliary Power Supply Cable
4. AUX I/O Connector for DUT



Note

Before operating the programmable power supply, short pin 4 to pin 5 on the AUX I/O connector. For more information, refer to *Installing the Input and AUX I/O Connector on the PXIe-4151*.

7.4.3. Verification Procedure

1. Reset the DUT.
2. Ensure that the warm-up time is observed for the DUT.

3. Perform self-calibration on the DUT, if required. Follow instructions identified in this procedure regarding self-calibration.
4. Ensure DUT is not generating any signals, and the output is turned off prior to making any connections.
5. Set the DUT to **DC Voltage** function.
6. Connect all test equipment as shown in **Figure 5**.



Caution

Before using any probes or accessories, ensure that they meet applicable safety requirements for the signal levels you may encounter.

Repeat 9 times, once for each voltage test point.

7. Set the level range, limit range, and limit on the DUT.
8. Set the level of the DUT to the test point according to **Table 9**.

Table 9: Current Load Regulation Test Point Configuration

| DUT Current Range | DUT Source Range | Test Point | DUT Model |
|-------------------|------------------|------------|-----------|
| 100 mA | 60 V | 15 V | PXIe-4150 |
| 100 mA | 60 V | 30 V | PXIe-4150 |
| 100 mA | 60 V | 60 V | PXIe-4150 |
| 1 A | 60 V | 15 V | PXIe-4150 |
| 1 A | 60 V | 30 V | PXIe-4150 |
| 1 A | 60 V | 60 V | PXIe-4150 |
| 10 A | 60 V | 15 V | PXIe-4150 |
| 10 A | 60 V | 30 V | PXIe-4150 |
| 10 A | 60 V | 60 V | PXIe-4150 |

| | | | |
|--------|------|------|-----------|
| 100 mA | 20 V | 5 V | PXIe-4151 |
| 100 mA | 20 V | 10 V | PXIe-4151 |
| 100 mA | 20 V | 20 V | PXIe-4151 |
| 1 A | 20 V | 5 V | PXIe-4151 |
| 1 A | 20 V | 10 V | PXIe-4151 |
| 1 A | 20 V | 20 V | PXIe-4151 |
| 25 A | 20 V | 5 V | PXIe-4151 |
| 25 A | 20 V | 10 V | PXIe-4151 |
| 25 A | 20 V | 20 V | PXIe-4151 |

9. Set the DUT to **2 PLC** for measurement.
10. Commit all settings to DUT.
11. Wait 2 seconds to ensure the system has adequate time to settle.
12. Take a current measurement from the DUT.
13. Verify the accuracy measurement against the test limit in **Table 8**.

8. Perform Adjustment

Recommend performing an adjustment at least once within the calibration interval. Adjustment automatically updates the calibration constants, the date, and the temperature in the DUT EEPROM. If the DUT passes the verification procedures within the As-Left test limits, an adjustment is not required. Proceed to the *Update the Onboard Calibration Information* section. Self-Cal shall be executed after the entire adjustment procedure to ensure that all ranges have been adjusted correctly.



Note

Performing self-calibration routine during external adjustment behaves differently than during normal operation. Do not exclude any

self-calibration routines as none of them are redundant and are necessary to complete the adjustment procedure.

8.1. Initialize for Adjust

Initiate an external calibration session. It is required to keep this session open throughout the entire adjust sequence. After each adjust procedure, commit the new constants to hardware. Then close the session after all adjustment procedures have been completed.



Figure 6 Initiate External Calibration Session vi

Execute a self-calibration after initiating the external calibration session to ensure that default tables are used during session. Without executing this self-calibration, the DUT will not create accurate correction factors.




Figure 7 Cal Self Calibrate vi

8.2. Voltage Accuracy Adjustment Procedure

8.2.1. Initial Test Connection



Note


Always refer to the specifications document for your device before connecting signals. Failure to observe the specified maximum signal ratings can cause a fire hazard or damage to the device connected to the DUT.



Note

Before using any probes or accessories, ensure that they meet applicable safety requirements for the signal levels you may encounter.

Figure 8. Connections for Voltage Accuracy Adjustment Procedure



1. DUT
2. Auxiliary Power Supply
3. Auxiliary Power Supply Cable
4. Cal cable – "Banana" (NI 101295A-01)
5. DMM
6. HI Sense signal cable
7. HI signal cable from DUT (Positive polarity defined as voltage measured on NI > LO)
8. LO Sense signal cable
9. LO single wire from DUT (Positive polarity defined as voltage measured on NI > LO)
10. AUX I/O Connector for DUT

**Note**

Before operating the programmable power supply, short pin 4 to pin 5 on the AUX I/O connector. For more information, refer to *Installing the Input and AUX I/O Connector on the PXIe-4151*.

8.2.2. Adjustment Procedure

1. Ensure DUT is not generating any signals, and the output is turned off prior to making any connections.
2. Set the DUT function to **DC Voltage**.
3. Connect all test equipment as shown in **Figure 8**.

**Note**

Before using any probes or accessories, ensure that they meet applicable safety requirements for the signal levels you may encounter.

Repeat 4 times, once for each test point.

4. Set the level range, limit range, and limit on the DUT.
5. Set current limit to **100 mA**.
6. Set current range to **100 mA**.
 - a. Set current set point to **0 A**.
7. Configure the DMM
 - a. Set the DMM NPLC to **100**.
 - b. Set digits of resolution to **8.5**.
 - c. Set function to **DC Voltage**.

**Note**

Recommended to start with smallest signal level and iterate through test points according to increasing signal level.

8. Set the DMM to the voltage range according to **Table 10**.

9. Set the level of the DUT to the test point according to **Table 10**.



Note

Recommended to start with smallest signal level and iterate through test points according to increasing signal level.

Table 10: Voltage Test Point Configuration

| DUT Range | DUT Limit Range | Test Point | DMM Range | DUT Model |
|-----------|-----------------|------------|-----------|----------------|
| 6 V | 1 A | 100 mV | 1 V | PXIe-4150/4151 |
| 6 V | 1 A | 6 V | 10 V | PXIe-4150/4151 |
| 60 V | 1 A | 100 mV | 1 V | PXIe-4150 |
| 60 V | 1 A | 60 V | 100 V | PXIe-4150 |
| 20 V | 1 A | 100 mV | 1 V | PXIe-4151 |
| 20 V | 1 A | 20 V | 100 V | PXIe-4151 |

10. Wait 2 seconds to ensure the system has adequate time to settle.
11. An additional 4 minute wait is required when the DMM has changed either function or range.



Note

The additional 4 minute wait is to reduce thermal EMF and a requirement of using the DMM identified in this procedure.

12. Take a voltage measurement using the DMM.
13. Provide the DMM measurement to the DUT by calling the **niDCPowerCalAdjustVoltageLevel vi** or **niDCPower_CalAdjustVoltageLevel** function.
 - a. Input the DMM measurements as the **measured outputs**.
14. Input the DUT measurements as the **requested outputs**.
 - a. Input the specified level range as the **range**.




Figure 9. Cal Adjust Voltage Level vi

15. Execute calibration self-calibration on DUT. This process will update the voltage correction factors, which will impact the current adjustment.





Figure 10. Cal Self Calibrate vi

8.3. Adjusting Current Accuracy Procedure

8.3.1. Initial Test Connection

Figure 11. Connection for Adjusting Current Accuracy Procedure



1. DUT
2. Auxiliary Power Supply
3. Auxiliary Power Supply Cable
4. Cal cable – "Banana" (NI 101295A-01)
5. DMM
6. HI Sense signal cable
7. HI signal cable from DUT (Positive polarity defined as voltage measured on NI > LO)
8. LO Sense signal cable
9. LO single wire from DUT (Positive polarity defined as voltage measured on NI > LO)
10. AUX I/O Connector for DUT

**Note**

Before operating the programmable power supply, short pin 4 to pin 5 on the AUX I/O connector. For more information, refer to *Installing the Input and AUX I/O Connector on the PXIe-4151*.

8.3.2. Adjustment Procedure

1. Ensure DUT is not generating any signals, and the output is turned off prior to making any connections.
2. Set the DUT to **DC Current** function.
3. Connect all test equipment as shown in **Figure 11**.

**Caution**

Before using any probes or accessories, ensure that they meet applicable safety requirements for the signal levels you may encounter.

Repeat 4 times, once for each test point.

4. Set the level range, limit range, and limit on the DUT.
 - a. Set voltage limit to **6 V**.
 - b. Set voltage range to **6 V**.
5. Configure the DMM
 - a. Set the DMM NPLC to **100**.
 - b. Set digits of resolution to **8.5**.
 - c. Set function to **DC Current**.

**Note**

Recommended to start with smallest signal level and iterate through test points according to increasing signal level.

6. Set the DMM to the voltage range according to **Table 11**.

7. Set the level of the DUT to the test point according to **Table 11**.



Note

Recommended to start with smallest signal level and iterate through test points according to increasing signal level.

Table 11: Current Test Point Configuration

| DUT Range | DUT Limit Range | Test Point | DMM Range | DUT Model |
|-----------|-----------------|------------|-----------|----------------|
| 100 mA | 6 V | 1 mV | 100 mA | PXIe-4150/4151 |
| 100 mA | 6 V | 100 mA | 100 mA | PXIe-4150/4151 |
| 1 A | 6 V | 10 mA | 100 mA | PXIe-4150/4151 |
| 1 A | 6 V | 1 A | 1 A | PXIe-4150/4151 |

8. Wait 2 seconds to ensure the system has adequate time to settle.
9. An additional 4 minute wait is required when the DMM has changed either function or range.



Note

The additional 4 minute wait is to reduce thermal EMF and a requirement of using the DMM identified in this procedure.

10. Take a current measurement using the DMM.
11. Provide the DMM measurement to the DUT by calling the **niDCPowerCalAdjustCurrentLimit vi** or **niDCPower_CalAdjustCurrentLimit** function.
 - a. Input the DMM measurements as the **measured outputs**.
12. Input the DUT measurements as the **requested outputs**.
 - a. Input the specified level range as the **range**.




Figure 12. Cal Adjust Current Limit vi

13. Execute calibration self-calibration on DUT. This process will update the current correction factors, which will impact the commit portion of the adjustment.




Figure 13. Cal Self Calibrate vi

8.4. Closing Adjustment Session

Close the session and commit the new constants to hardware by calling the **niDCPower Close External Calibration vi** or **niDCPower_CloseExtCal** function and specifying Commit as the **calibration close action**.

8.5. Running Self Cal

1. Ensure that all connections to the DUT are removed and disconnected.
2. Complete the following steps to conduct self-calibration using Measurement & Automation Explorer (MAX).
3. Launch Measurement Automation Explorer (MAX).
4. Select **My System»Devices and Interfaces»[DUT model name]**.

5. Start self-calibration using one of the following methods:
 - a. Click **Self-Calibrate** in the upper right corner of MAX.
 - b. Right-click the name of the DUT in the MAX configuration tree and select **Self-Calibrate** from the drop-down menu.

9. Perform Reverification

Perform all tests in the Verification section after completing Adjustment. This verification compares the As-Left limits with measurement data collected after the DUT adjustment. The As-Left limits may be tighter than the As-Found limits.

10. Update the Onboard Calibration Information

If the DUT passes all verification procedures successfully, meets the As Left limits, and the adjustment procedure is not going to be executed, then the calibration date can be updated by completing the following steps.



Note

NI recommends following the adjustment procedure in order to update the calibration constants and renew the device calibration interval.

1. Open a session to the DUT with either the **niDCPower Initialize External vi** or **niDCPower_InitExtCal** function.
2. Specify commit in the calibration close action when closing the session with either the **niDCPower Close External Calibration vi** or **niDCPower_CloseExtCal** function.

Use either Measurement Automation Explorer (MAX) or NI System Configuration API to set a calibration due date for the DUT or to clear the calibration due date. NI suggests a minimum calibration due date of the date of external calibration plus the recommended external calibration interval.

3. In MAX, navigate to the External Calibration section of the Settings tab to update the Calibration Due Date entry.
4. Alternatively, use the Update Calibration vi in the NI System Configuration API to set the calibration due date.

11. Revision History

| Revision | Section | Changes |
|------------------------|---------|---|
| 379060A-01 May 2025 | All | This is the initial release version of the PXIe-4150 and PXIe-4151 Calibration Procedure. |

12. NI Services

Visit ni.com/support to find support resources including documentation, downloads, and troubleshooting and application development self-help such as tutorials and examples.

Visit ni.com/services to learn about NI service offerings such as calibration options, repair, and replacement.

Visit ni.com/register to register your NI product. Product registration facilitates technical support and ensures that you receive important information updates from NI.

NI corporate headquarters is located at 11500 N Mopac Expwy, Austin, TX 78759-3504, USA.

Information is subject to change without notice. Refer to the *NI Trademarks and Logo Guidelines* at ni.com/trademarks for more information on National Instruments trademarks. Other product and company names mentioned herein are trademarks or trade names of their respective companies. For patents covering National Instruments products/technology, refer to the appropriate location: **Help»Patents** in your software, the `patents.txt` file on your media, or the *National Instruments Patents Notice* at ni.com/patents. You can find information about end-user license agreements (EULAs) and third-party legal notices in the readme file for your NI product. Refer to the *Export Compliance Information* at ni.com/legal/export-compliance for the National Instruments global trade compliance policy and how to obtain relevant HTS codes, ECCNs, and other import/export data. NI MAKES NO EXPRESS OR IMPLIED WARRANTIES AS TO THE ACCURACY OF THE INFORMATION CONTAINED HEREIN AND SHALL NOT BE LIABLE FOR ANY ERRORS. U.S. Government Customers: The data contained in this manual was developed at private expense and is subject to the applicable limited rights and restricted data rights as set forth in FAR 52.227-14s, DFAR 252.227-7014, and DFAR 252.227-7015.

© 2024-2025 National Instruments Corporation. All rights reserved.